			SR No	Part Description	MOC	Qty]
			1	Bracket	SS316	1	Н
			2	U-Bolt	SS316	2	1,
			3	Washer	SS304	4	- J
			4	Nut	SS304	4	11
	2 7 3	20 20 UP 90° R 0.74 0		ŧ ŧ			I H G
	<u>10</u>						E D C
MANUFACTURING AND HANDLING INSTRUCTIONS :-	Г	Mounting U-Bolts an	d Nuts to	he provided alon	gwith Bra	cket	+-1
All Dimensions are in mm. Unless otherwise sta							В
1) HANDLE WITH CARE. MOUNTING BRACKET				Material : AS PER BOM			
 NO DENTS OR TOOL MARKS AFTER MACHINING. NO WIRE BURRS ALLOWED. NO CHATTERING ON MACHINED SURFACE. NO VISIBLE MACHINING LINE PERMITTED. DO NOT USE POLISH PAPER OR BUFFING ON MACHINED AREA. UNSPECIFIED TOLERANCE IS ±0.2 		All dimensions are in mm. Dimension	NTS	MB0	0101-S6		A
<u>NOTE</u> :- " * " INDICATES DIMENSION IS TO BE CHECKED WHILE INCOMING INSPECTION	www.havi.in info@havi.in	* This document is the property of VIP contained herein or relating to this doc	AL ENTERPRISES	Pvt. Ltd. No exploitation or relea	ase of any text		
16 15 14 13 12 11 10 9	8 7	6 5	4	3	2	1	-

L